

## State of Utah

## Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Gary E. Gray Resident Agent			
OGM	Karl Houskeeper Environmental Scientist III			

# **Inspection Report**

Permit Number:	C0150032			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, November 09, 2005			
Start Date/Time:	11/9/2005 9:00:00 AM			
End Date/Time:	11/9/2005 12:00:00 PM			
Last Inspection:	Thursday, October 13, 2005			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Cloudy, Temp 55 Deg F InspectionID Report Number: 782

> Accepted by: pgrubaug 11/14/2005

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: **EMERY** 

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### **Current Acreages**

Total Permitted	5,195.80	
Total Disturbed	10.70	
Phase I		
Phase II		
Phase III		

#### **Mineral Ownership**

**Types of Operations** ✓ Federal **✓** Underground State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending Amendments: Task #2291, Surface Buildings & Pond Map. Response received (Task #2350) October 11, 2005, under review.

Inspector's Signature

Date Wednesday, November 09, 2005

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 09, 2005

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		$\checkmark$	
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil	<b>✓</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		<b>✓</b>	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>✓</b>			
6.	Disposal of Excess Spoil, Fills, Benches		<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>✓</b>		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 09, 2005 Page 3 of 3

### 1. Permits, Change, Transfer, Renewal, Sale

Pending Amendments: Task #2291, Surface Buildings & Pond Map. Response received (Task #2350) October 11, 2005, under review.

#### 2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

#### 3. Topsoil

Topsoil from the parking addition in the USFS trailhead has been placed on top of the existing topsoil pile adjacent to the mine USFS road near the bridge. The newly placed topsoil has been seeded and mulched. The seed mix used was the permanent seed mix that is approved in the existing MRP.

#### 4.a Hydrologic Balance: Diversions

The culvert inlet at the base of the coal storage pad is plugged with coal. The operator documented the diversion and mobilized surface crews to correct the problem.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Task #2350 Sediment pond contours from pond cleaning is under review by the Division.

#### 4.d Hydrologic Balance: Water Monitoring

Second quarter 2005 water monitoring information is in the EDI website and uploaded. Water monitoring is current.

#### 18. Support Facilities, Utility Installations

The additional mine parking area has been constructed. The excavated slope has been seeded and mulched utilizing the permanent seed mix in the approved MRP. The excavated soil has been transported and stored on top of the existing topsoil pile adjacent to the USFS access road by the bridge. The topsoil pile has been seeded and mulched with the permanent seed mix contained in the approved MRP.